



SEAWARD


GMC-INSTRUMENTS GROUP

Why am I getting an error when using the PULS-R?

If the error message "Fitted SpO2 adapter does not match selected technology type" this can be resolved by selecting a PULS-R option in technology type. For example, change Nellcor (standard) to Nellcor (PULS-R) in the menu.

Ensure that both blue lights are on and the set up is as displayed in the image below.

Image not found or type unknown



If you require more help, please contact us at <https://www.seaward.com/us/enquire/>.